

GPOP - Issue Review System

Part Number: 68588637A\$, 68588639A\$, 68588643A\$, 68588647A\$, 68611543A\$,
68675763A\$, 68675764A\$, 68675765A\$, 68675766A\$, 68675777A\$

Part Description: MODULE Occupant Restraint

Issue Description: IF PROXI alignment is needed ONLY for the following parts please proceed with the next steps (68588647AB, 68611543AB, 68588646AC, 68620844AB, 68588637AB, 68588643AB, 68588638AC, 68620855AB, 68588639AB, 68588640AC, 68620856AB):
1. Unlock the ORC using the "Bosch WL ORC Lock Unlock Procedure" wiTECH Guided Diagnostic routine 2. Perform the "PROXI Configuration Alignment for the ORC" 3. Re-run the "Bosch WL ORC Lock Unlock Procedure" to Lock the ORC For a detailed explanation please refer to SOL S2308000016 Rev. B Do NOT perform the above steps if you have the following parts:
68675763AA, 68675777AA, 68675764AA, 68675765AA, 68631466AA, 68631463AA, 68631464AA, 68631465AA,