



STAR ONLINE PUBLICATION



Case Number: S2409000003

Release Date: July 2024

Symptom/Vehicle Issue: Engine Oil Leak

Customer Complaint/Technician Observation: Customer complaint may include fluid leaking from vehicle.

Discussion: Upon inspection, tech may find a crack at the oil pan drain plug area (Fig. 1). Repair as necessary. R&R oil pan according to service information published in Service Library. Oil drain plug should be torqued to 27Nm \pm 3Nm (20Ft/Lbs).



Note: Oil pan drain plug should NEVER be installed with power tools

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found