



SIB 65 02 24

2024-07-17

SERVICE SOLUTION: S 1000 XR DWA Alarm Will Not Activate With Key

**MODEL**

Model	Model Description
K69	S 1000 XR

**SITUATION**

The DWA (Anti-Theft Alarm) of the S 1000 XR cannot be activated with the radio operated key due to a software error.

**PROCEDURE**

The solution will be released with I-Level K001-24-07-510 expected to be available with ISTA version 4.48.2 Has been released.

**QUESTIONS REGARDING THIS BULLETIN**

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture\\_as\\_pdf 65 02 24 SESO S 1000 XR DWA.pdf](#)

