

## Volvo VAH/VHD Headlights

**Service Category** Service

**Section** Function Group 352

**Technician Skill Level** A

**Market** North America

### Applicability

**VOLVO**

Years	Models
2022	VAH/VHD

### Introduction

Volvo Trucks has determined that certain model year 2022 VHD/VAH vehicles could experience headlight vibration, which makes the headlights appear to bounce at idle. A new and redesigned headlamp assembly is now available to correct the vibration issue. Follow the instructions below to replace both headlamp assemblies with the new improved headlamps.

### Production Change Information

This bulletin applies to vehicles built within the specified production changes below.

Brand	Engine	Emission Level	Starting Build Date	Ending Build Date
Volvo	D11, D13	EM-US17, EM-US21	11-January-2021	27-August-2021

### Warranty Information

<b>This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process.</b>		
Claim Type (used only when uploading from the Dealer Bus. Sys.)		<b>B</b>
<b>Main Labor Code</b>	<b>Description</b>	<b>Hours</b>
3521-03-02-01	Headlamp Assembly, Replacement X2	1.2
<b>Causal Part</b>	<b>24178468/24178467</b>	
<b>SCC Authorization Code</b>	<b>S3305</b>	
<b>Expiration Date</b>	<b>December 30, 2024</b>	

## Volvo VHD Headlights

---

### Parts Information

Part Numbers	Part Names	Quantity
24178468	Headlamp - LH	1
24178467	Headlamp - RH	1

### Required Tools & Equipment

- None

### Calibration Information

- None

### Repair Procedure

1. Replace both driver side and passengers side headlamp assemblies following operation **3521-03-02-01Headlamp Assembly, Replacement** in Impact.