


## Drivers Information Display (DID) Inoperative After Cluster Replacement And Programming

Published Date 9 July 2024

### Valid For

Mack AN,GR,CHU,CXU,PI and Volvo VNR,VNR,VNX,VAH,VHD Model Year 2021 to 2024 with a Mid 140 instrument cluster

After cluster replacement and programming, the Driver Information Display (DID) may not function as designed. See Image below.



New software has been released to fix this issue. Please reprogram the IC and confirm the repair.

**NOTE:** In the rare case the IC will not program please run accessory kit # **85170265**.

### Related links and attachments

No links or attachments available



#### Share

to others that might find it helpful



#### Feedback

[Give feedback](#)

to help improve the content of this  
article