



Service Bulletin

Bulletin No.: 24-NA-135

Date: July, 2024

INFORMATION

Subject: Information on Block Heater Cord Installation (K05)

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2024	2025	-	-	All	All
Chevrolet	Equinox	2025	2025	-	-	All	All
	Traverse	2024	2025				
GMC	Acadia	2024	2025	-	-	All	All

Involved Region or Country	North America
Additional Options (RPOs)	Equipped with Block Heater (RPO K05)
Condition	Some technicians may notice that the block heater cord is not installed from the plant.
Cause	Block heater cord is now a dealer install item.

Information

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Block heater cord installation will be treated as a dealer install item. Follow service information located in the Accessories Manual > Accessories > Performance Accessories > Engine Coolant Heater Package Installation (K05).

Doc ID : 6665963 for Acadia, Traverse, Enclave.

Doc ID: 6673247 for Equinox

Utilize labor code 0590032 PDI Dealer Installed - Factory Invoiced Options for labor time.

Version	1
Modified	Released July 17, 2024

