

# McLaren Artura Interior Rear View

## Mirror Rattle

---

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

### Document Information

**Location:** Interior

**Topic:** Rattle from interior rear view mirror shroud when driving

**Condition:** Intermittent

**Diagnostic Trouble Codes:** N/A

### Measure

In the event that a rattle is audible from within the rear view mirror shroud, please complete the following measure as a first action.

- Remove the rear view mirror shroud trim complete
- Locate the 4 x metal clips circled below



- Apply anti-vibration Tesa tape to the 4 x metal clips as shown below

RESTRICTED



Care Point: Do not cover the slotted area on the back of the clip (OK/NOK condition shown below)



OK - tape does not cover slot



NOK - tape covers slot

- Rebuild and test vehicle

## Parts Information

Locally sourced anti-vibration Tesa tape

## Attachments

N/A

**This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.**