



STAR ONLINE PUBLICATION



Case Number: S2408000084



Release Date: August 2024

Symptom/Vehicle Issue: ABS Brake Lamp on Diagnostic Trouble Code (DTC) C0508-00 Right Front Wheel Speed Sensor Circuit Low

Customer Complaint/Technician Observation: The owner complains of the Anti-Lock Brake Lamp on after a recent repair service. The technician observed, multiple DTCs.

C0508-00 - Right Front Speed Sensor Circuit "A" Circuit Low
C2227-00 - ABS Disabled
U140A - Implausible Right Front Message
U0415-00 - Implausible Data from Anti-Lock Brakes
U1412-00 - Implausible Vehicle Speed

Repair Procedure: Inspect the right front harness routing for signs of harness pinching for the right front speed sensor. Reposition the harness as needed to resolve.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.