

SS 765 - ECP Solenoid Valve Interim Replacement Parts

Applicable Vehicles

47X and 49X vehicles with ECP solenoid valves

Symptoms

ECP solenoid failures that require replacement of the solenoid - for example, lift axle does not raise or drop.

Issue

Current solenoid parts have been replaced with an interim, soft-tooled part ahead of production changeover to a revised ECP solenoid. These soft-tooled parts should be used instead of the parts listed in Excelerator.

Solution

The following two parts have been released and are available in the PDCs:

12-33827-000 replaces solenoid 12-29442-000

12-33827-001 replaces solenoid 12-29442-000

Labels :

47X 49X 57X

Add tags

 1 Kudo