

Technical information

Daimler Buses

TI No.: 54.00T24289A

Distribution list: D

Distribution date:

17.07.2024

Valid until: 31.12.2026

The point of contact is the Daimler Buses after-sales service in each country

Model: Tourrider USA

MODEL DESIGNATION 410840; 410850

(BM):

TITLE: Tourrider USA - fuse assignment in the vehicle could differ from documentation

COMPLAINT

The fuse assignment in the vehicle could differ from the applicable documentation.

CAUSE

Documentation and production errors.

REMEDY

Compare the bus-specific fuse assignment on the main switch panel, auxiliary switch panel and power distribution board with the currently applicable specified state and correct if necessary.

It will then be necessary to exchange the adhesive labels of the fuse assignments in the vehicle to reflect the updated state.

MEASURE TYPE

The scope of the work is carried out as part of a Customer Service measure (KDM).

INFORMATION

This Customer Service measure is carried out by trained workshop employees together with the development specialist department.

Given the various build statuses and the associated differences in the amount of effort required, there is no possibility of setting a flat rate value for the standard working time.

OPERATION TEXTS

Operation no. Operation text

12-2103 Correct fuse assignment

Working time/h CommentZM (time prescribed
by team manager)

The times apply for work at an hourly rate.

DEFECT NUMBER**Defect no.: Designation**

5491897

CODEWORD

5400T24289

INTRODUCTION OF MODIFICATIONS INTO SERIES PRODUCTION

01.01.2024

WARRANTY AND GOODWILL SETTLEMENTS

Field measure type KDM (Customer Service measure): 100 % of costs will be accepted.

BUS/MCC

pp.

Markus Fischer

BUS/MCC-O

pp.

Sabine Stephan

This document may contain confidential information. Distribution
outside the production plant's distribution list is not permitted.

For information only. Subject to ongoing technical development. Not
subject to the amendment service.