



SSM 52683 2024 F-150 Lightning - DTC B15F0:15 Setting In The IPMA When A Diagnostic Self-Test Is Performed

Some 2024 F-150 Lightning vehicles may set diagnostic trouble code (DTC) B15F0:15 in the image processing module A (IPMA) when a diagnostic self-test is performed. This may be due to an IPMA communication error within a specified timeframe. DTC B15F0:15 does not affect vehicle durability with no effect on vehicle operation and no additional diagnosis or service is required for this condition at this time. Replacement or reprogramming of the IPMA will not resolve this condition. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition and will be released over-the-air (OTA) expected in Q4 2024. Software will update automatically if vehicle connectivity is enabled in the vehicle's settings. Schedule a service visit for customers who have disabled vehicle connectivity or who report that they did not receive the update by December 2024. Monitor OASIS for additional information.