

**Technical Service Bulletin (TSB)**  
**Flash: Radio Frequency Hub Module (RFHM) Updates**

<b>REFERENCE:</b>	<b>TSB:</b> 08-169-24 REV. A <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	July 31, 2024	<b>REVISION:</b>	08-169-24
<b>VEHICLES AFFECTED:</b>	<b>2024 (WL) Jeep Grand Cherokee / Grand Cherokee L</b> This bulletin applies to vehicles built on or before May 13, 2024 (MDH 0513XX).	<b>MARKET APPLICABILITY:</b>			
		<input checked="" type="checkbox"/> NA		<input checked="" type="checkbox"/> MEA	
		<input checked="" type="checkbox"/> SA		<input type="checkbox"/> IAP	
		<input checked="" type="checkbox"/> EE		<input type="checkbox"/> CH	
<b>CUSTOMER SYMPTOM:</b>	<p><b>Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs):</b></p> <ul style="list-style-type: none"> <li>• B1A10-00 - RKE FOB 1 Battery Low.</li> <li>• B1A11-00 - RKE FOB 2 Battery Low.</li> <li>• B23D7-14 - Gated Park Control - Circuit Short To Ground Or Open.</li> </ul> <p><b>Customers may also experience one or more of the following:</b></p> <ul style="list-style-type: none"> <li>• Vehicle won't start unless the fob is pressed to KIN.</li> <li>• Key fob not detected when inside vehicle.</li> <li>• Passive Entry (PE) intermittently inoperative.</li> <li>• Keyless Ignition Node (KIN) unresponsive.</li> <li>• Welcome feature does not activate at times.</li> </ul>				
<b>CAUSE:</b>	RFHM software				

**This bulletin supersedes Technical Service Bulletin (TSB) 08-169-24, date of issue July 23, 2024, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include converting this to an information only TSB.**

**This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-106, date of issue July 23, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.**

**DISCUSSION:**

The solution is currently unavailable and will be re-released at a future date.

**POLICY:**

Information Only

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*