



SSM 52723 2024 F-150 Non-Lightning - DTC B15F0:15 Setting In The IPMA When A Diagnostic Self-Test Is Performed - Built On Or Before 03-Jun-2024

Some 2024 F-150 non-Lightning vehicles built on or before 03-Jun-2024 may exhibit diagnostic trouble code (DTC) B15F0:15 in the image processing module A (IPMA) when a diagnostic self-test is performed. This may be due to an IPMA communication error within a specified timeframe. To correct this condition, reprogram the IPMA using the latest software version of the Ford Diagnosis and Repair System (FDRS) scan tool. For claiming, use causal part 14G647 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.