



Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2000-2024	All	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2045803/5	7/11/24	00-16-02TT	Update to model and model year applicability.
2045803/4	10/2/20	00-16-02TT	Update to model and model year applicability.
2045803/3	9/28/18	00-16-02TT	Update to model and model year applicability.
2045803/2	6/12/17	00-16-02TT	Update to latest standard.
2045803/1	10/28/16	TT 00-16-02	Original publication.

Technical Background

During certain repairs or component replacements, fastener replacement is **Mandatory**. Review the ELSA repair instructions for the components being serviced to determine if there are fasteners requiring mandatory replacement.

Examples would include, but are not limited to these areas:

- Various Engine bolts such as the cylinder head, crank pulley and flywheel, etc.
- Brake Calipers, Ball Joint nuts, Strut to Body nuts, Drive Axle to Hub, etc.

Steering Wheel to Column, Tie Rod to Wheel Bearing Housing, etc.

Service

N.A.



00-16-02TT - Mandatory Fastener Replacement

Release date: 7/11/2024

Additional Information

© 2024 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.