



SSM 52758 2025 Aviator - Diagnostic Trouble Code (DTC) B1519:13 Setting In The DCME, DCMF, DCMG And/Or DCMH

Some 2025 Aviator vehicles may have diagnostic trouble code (DTC) B1519:13 stored in the door control module E/F/G/H (DCME, DCMF, DCMG and/or DCMH). If this DTC is identified during ePDI or normal diagnostics for various concerns, this DTC does not affect vehicle durability and no additional diagnosis or service is required for this DTC at this time. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition that is expected in Q4 2024. Replacement or reprogramming of these modules will not resolve this DTC. Monitor OASIS for additional information and schedule service appointments for customers once the repair becomes available.