



## **SSM 52761 2025 Explorer/Aviator/Police Interceptor Utility - Flashing Powertrain Malfunction (Wrench) Indicator In Transport Mode With DTC P112A**

Some 2025 Explorer/Aviator/Police Interceptor vehicles may exhibit a flashing powertrain malfunction (wrench) indicator while in transport mode with diagnostic trouble code (DTC) P112A stored in the powertrain control module (PCM). This may be due to excessive engine starts while the vehicle is in transport mode. To correct the condition, deactivate transport mode. Refer to Workshop Manual (WSM), Section 419-10 > General Procedures. Cycle the ignition to RUN. If the concern still exists, perform normal diagnostics, refer to WSM Section 303-07.