



# Technical Service Bulletin

---

## 93 PSS Q4 drive system fault P164700/P060C00

93 24 69 2074415/2 July 10, 2024. Supersedes Technical Service Bulletin Group 93 number 24-66 dated July 1, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2024	All	Not Applicable

## Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (Add software ETA)
1	07/01/2024	Initial publication

This bulletin applies to MY24 Q4 vehicles only.

### Customer states:

Drive system fault in instrument cluster

### Workshop findings:

The following DTCs are stored in the Engine Control Module, J623 (address word 0001):

**P164700 symptom 44180 and/or 44181**

and

**P060C00 symptom 43863**

## Technical Background

Not applicable.

## Production Solution

Not applicable.

## Service



# Technical Service Bulletin

---

Required

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Required Parts and Tools

Delete if not required.

## Additional Information

All parts and service references provided in this TSB (XXXXXX) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.