



Technical Service Bulletin

93 Q4 drive system fault P30A000 - Intermediate circuit capacitor not discharged, front power electronics
93 24 93 2074705/1 July 31, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2022 – 2023	All	Not Applicable

Condition

Customer states:

The electric drive system warning lamp lights up in the dash panel insert.

and/or

Various warning lamps light up in the dash panel insert.

Workshop findings:

The customer statement can be reproduced. The following DTC and symptom code(s) is/are logged in the electric drive control unit 2 -JX4-, (address word 00CE):

- **P30A000:** Intermediate circuit capacitor not discharged - symptom: 42124.

Technical Background 1

Software issue in electric drive control unit 2 (diagnostic address: 00CE).

Production Solution

Optimized software implemented in electric drive control unit 2 (diagnostic address: 00CE).

Service

Please perform Campaign **91EV**.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.
Service Number:	9370



Technical Service Bulletin

Damage Code:	0040		
Labor Operations:	Charge battery	2706 8950	See SRT with associated operations
	Check vehicle (bus sleep mode)	0689 0199	10 TU
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2074705/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2074705**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.