

WRJ9 Stop delivery - Retighten the screw connection of the rear bumper and trailer hitch

WRJ9 Stop delivery - Retighten the screw connection of the rear bumper and trailer hitch

ID Number	WRJ9
Model(s)	Cayenne (9YA/9YB)
Model Year	2024
Number of Affected VINs	39
Issue Description	On the affected vehicles, it is possible that the screw connection of the rear bumper/trailer hitch was not tightened to the prescribed tightening torque. For this reason, the screw connection of the rear bumper or trailer hitch must be retightened with the prescribed tightening torque before delivery to the customer
What Dealers Should do	Please repair the affected vehicles as soon as possible, the remedy is immediately available and the TI is attached below.
TI Number	TI is posted below, and will not be available in PCSS

Attachments

- [WRJ9 Stop Delivery_EN.pdf](#)
- [VIN_List_Report_WRJ9_2024-07-01_V2.xlsx](#)