

# WRH5 Stop Delivery - Add Charge Timer and Reset Central Computer to Factory Defaults

---

## WRH5 Stop Delivery - Add Charge Timer and Reset Central Computer to Factory Defaults

ID Number	WRH5
Affected Models	Taycan
Model Years	2025
VIN List	Attached
Number of Affected Vehicles	268
Issue Description	<p>Due to a software error, it is possible that the high-voltage charger (OBC) is not set to energy-saving mode after the vehicle is switched off.</p> <p>Under certain circumstances, this can result in increased closed-circuit current consumption and can thus discharge the vehicle electrical system battery.</p> <p>To avoid this, a charging timer is added once in the central display (PCM) of the affected vehicles and then the central computer is reset to factory settings before delivery to the customer.</p>
What should Porsche Centers do?	<p>Vehicles must not be delivered to customers until the remedy is complete.</p> <p><b>Please repair the affected vehicles as soon as possible, the remedy is immediately available as of the time of this posting (7/2/24).</b></p>
TI Number	<a href="#">No. 85-24</a>

---

### Attachments

- [1. VIN\\_List\\_Report\\_WRH5\\_2024-07-02\\_V2.xlsx](#)