

# WPN5 Workshop Campaign - Replacing front air-spring strut

---

## WPN5 Workshop Campaign - Replacing front air-spring strut

ID Number	WPN5
Models	Taycan (Y1A / Y1B / Y1C)
Model Years	2023
VIN List	Attached
Number of Affected VINs	55
Issue Description	<p>There is a possibility that the screw connection of the support mount housing on the air suspension strut on the affected vehicles was not carried out according to specifications.</p> <p>If this is the case, it cannot be ruled out that a stud of the support mount housing could loosen over the vehicle's service life and in a sporty-dynamic driving style. The customer can notice this through a rattling noise on the front axle.</p>
What dealers should do	<p>Please arrange for this action to be carried out on the affected vehicles within the market responsible area. <b>Parts can be ordered and the remedy is immediately available .</b></p>
TI	<a href="#">No. 155/23</a>

## Warranty processing

### Validity:

This workshop campaign will be carried out up to 06/06/2029 and will be completed by the specified date. Please note that warranty claims can only be processed up to this date.

### Scope 1:

## WPN5 Workshop Campaign - Replacing front air-spring strut

Replacing left air-spring strut on front axle - Valid for vehicles with rear wheel drive

Damage Number	WPN5 66 000
Repair Code	2
Labor time	851 TU

### Scope 2:

Replacing air-spring strut on the right front axle - Valid for vehicles with rear wheel drive

Damage Number	WPN5 66 000
Repair Code	2
Labor time	851 TU

### Scope 3:

Replacing left and right air-spring struts on the front axle - Valid for vehicles with rear wheel drive

Damage Number	WPN5 66 000
Repair Code	2
Labor time	1006ZE

### Scope 4:

Replacing left and right air-spring struts on the front axle - Valid for vehicles with rear wheel drive  
(Only for vehicles for which only the replacement of an air-spring strut is planned, but air-spring struts on both sides have been replaced depending on mileage)

Damage Number	WPN5 66 000
Repair Code	2
Labor time	1006 TU

### Scope 5:

Replacing air-spring strut on left front axle - Valid for vehicles with all-wheel drive

Damage Number	WPN5 66 000
Repair Code	2
Labor time	868 TU

### Scope 6:

Replacing air-spring strut on the right front axle - Valid for vehicles with all-wheel drive

Damage Number	WPN5 66 000
Repair Code	2
Labor time	868 TU

### Scope 7:

Replacing left and right air-spring struts on the front axle - Valid for vehicles with all-wheel drive

Damage Number	WPN5 66 000
Repair Code	2
Labor time	1041 TU

### Scope 8:

Replacing left and right air-spring struts on the front axle - Valid for vehicles with all-wheel drive

## WPN5 Workshop Campaign - Replacing front air-spring strut

(Only for vehicles for which only the replacement of an air-spring strut is planned, but air-spring struts on both sides have been replaced depending on mileage)

Damage Number	WPN5 66 000
Repair Code	2
Labor time	1041 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

---

### **Attachments**

1. [WPN5 Campaign VIN Lists V2 07.26.2024.xlsx](#)