

# WPS1 Workshop campaign – Checking pressure sensors and replacing them if necessary

---

## WPS1 Workshop campaign - Checking pressure sensors and replacing them if necessary

ID Number	WPS1
Models	Cayenne E-Hybrid (9YA / 9YB) Panamera E-Hybrid (971)
Model Year	2020 - 2023
VIN List	Attached
Number of Affected VINs	2835
Issue Description	<p>Due to a manufacturing error at the supplier, pressure sensors for the refrigerant circuit purchase that do not meet the required specifications were potentially installed in the affected vehicles.</p> <p>The failure of one or both pressure sensors in the refrigerant circuit can therefore not be ruled out over the lifetime of the vehicle. As a result, there is a possibility that the proper functioning of the air conditioning and battery cooling system is not given. This can lead to an increased temperature of the high-voltage battery.</p>
What Dealers Should Do	<p>Please arrange for this action to be carried out on the affected vehicles during the next workshop visit. <b>Parts can be ordered and the remedy is immediately available</b></p>
TI	<a href="#">No. 04/24</a>

## Warranty processing

Validity:

This workshop campaign will be carried out up to 06.06.2029 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

### Scope 1 to Scope 8:

- Cayenne (9YA / 9YB)

Damage Code	WPS1 66 000
Repair Code	1/2
Labor time	126 - 350 TU

### Scope 9 to Scope 16:

- Panamera (971)

Damage Code	WPS1 66 000
Repair Code	1/2
Labor time	113 - 322 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

---

## Attachments

1. [Corrected WPS1 Campaign VIN Lists V2 07.26.2024.26.2024.xlsx](#)