

WRM4 Stop Delivery - Re-programming DME control unit

WRM4 Stop Delivery - Re-programming DME control unit

ID Number	WRM4
Models	Cayenne (9YA / 9YB)
Model Years	2024
VIN List	Attached
Number of Affected Vehicles	4
Issue Description	<p>On the affected vehicles, the software of the DME control unit does not meet the required specifications.</p> <p>For this reason, the DME control unit must be reprogrammed on the affected vehicles before delivery to the customer.</p>
What should Porsche Centers do?	<p>Vehicles must not be delivered to customers until the remedy is complete.</p> <p>The remedy is now available as of 7/30/24.</p> <p>Please perform Automatic programming of the DME control unit with the PIWIS Tester Release 42.800.060 (or higher).</p>
TI Number	There is no TI for this campaign. Please click the "i" in PCSS to view the programming sequence.

Attachments

- [1. VIN_List_Report_WRM4_2024-07-30_V2.xlsx](#)