

L461 FRONT CAMERA IMAGE UPSIDE DOWN

Concern

- During new vehicle inspection, it may be found that the front camera image display is upside down. (Side and Rear cameras not affected)

Technical description

- L461 Front camera is mounted 180 degrees opposite to L460.
- NFSM may be incorrectly calibrated to L460 setting causing the front camera image to appear upside down.

Recommended action

- Workflow to correct this condition through NFSM – Factory Reset application has now been made available in TOPIx.
- Follow Symptom selection below to access:

2 Test Plan

SELECTED SYMPTOMS

Electrical > Driver Assistance Systems > Camera System > Front Proximity Camera Image Displayed Upside Down

TEST PLAN NIT when relevance determined: 24-Apr-2024 12:24:40

Tests relevant to the chosen symptom and DTCs present on the vehicle are displayed below. If you require an alternative test, please 'Select a Test' where a search function is available

Select a test

Recommended Action	VCI	Actions	Results
1 Front Proximity Camera Image Displayed Upside Down - Test	Required	Run	
● Launch Datalogger	Required	Run	
● Launch Wiring Diagrams	Not required	Run	

You can select one or more DTC(s) to investigate by reading their helptext and snapshot data. If the helptext actions guide you to the root cause, you can copy/paste this text into the 'technician comments' box.

Investigate a DTC

ROOT CAUSE

Has root cause been found? ✘

Component categories:

All

Component

Select a component

Technician Comments

Please include technician write-up on how fault created based on this workflow.

RAISED TECHNICAL SUPPORT ISSUES

Electrical > Driver Assistance Systems > Camera Systems > Front Proximity Camera Image Displayed Upside Down