

COOLANT LEVEL CHECK FOR MHEV SYSTEM – 4.4L

Customer Voice:

- EV not available warning on Instrument cluster.

Technical Description:

- The coolant level is insufficient and causes a low coolant warning code in the DC/DC convertor.

Status:

- Please check the coolant level for the MHEV system.
- The procedure will require removing the MHEV battery for access.
- The two tools you will need are JLR-303-1649 and HU-919.
- It is a sealed system, you will be able to pressure test when removed from vehicle.
- NOTE: Please follow the TOPIx procedure step by step for draining and filling.

Refer to TOPIx: 613-01 Cooling System - [+] MHEV, General Procedures

Range Rover

- 24MY Range Rover
- 24MY Range Rover Sport

