

## LEAKING COOLANT PUMPS – 2.0L/P4

### -Customer Voice:

- Low coolant light on or smell of coolant from engine area.

### Technical Description:

- The engine cooling pump is misting from the front seal onto the coolant pump pulley.

### Status:

- Follow TOPIX workflow. It will direct you to:
  - Please inspect and take a photo of outer casting under a UV light, showing the whole component.
  - Please inspect and take a photo under a UV light of the inside of each of the spaces between the hub spokes.
- Raise a TA for the attention of Local Engineering who will dispatch sample bottle.
- USE SAMPLE BOTTLE ONLY to take 4-ounce coolant sample before repair.
- Dispatch coolant sample using FedEx label provided.
- Retain removed water pump for collection via PRR.

#### Range Rover

- 17-24MY RR Evoque
- 18-24MY RR Velar

#### Defender


- 20-23MY Defender

#### Discovery

- 17-24MY Discovery
- 17-24MY Discovery Sport

#### Jaguar

- 17-24MY E-PACE
- 17-24MY F-PACE
- 17-24MY XF
- 17-21MY XE



### 303-03B: Engine Cooling - INGENIUM I4 2.0L Petrol

