

## SV Signature Suite – 2<sup>nd</sup> Row Deployable Table Not Stowing

### Customer Voice:

- The 2<sup>nd</sup> row deployable table is not stowing and stays deployed.

### Technical Description:

- The deployable table for the 2<sup>nd</sup> row seats may not stow once deployed due to a fault with a microswitch in the table assembly.

### Status:

- The microswitch has been released as a service part, part number LR189749
- **SSM 76140** has been published to address this concern, providing repair guidance.

### Range Rover

- 23MY Range Rover (SV model variants Only)

