

Reference	SSM76132
Models	New Range Rover Sport / L461
Title	6D drain and fill unit potential fluid hose union loose
Category	Chassis
Last modified	09-Jul-2024 00:00:00
Symptom	304000 Suspension System
Attachments	6D Hose Check Process 1.pdf (6D Hose Check Process 1.pdf) 6D Hose_Union Check Both Ends.JPG (6D Hose_Union Check Both Ends.JPG)

Content

Note: Range Rover Sport SV only

Issue: There is potential for a hose union(s) to loosen within the 6D drain and fill unit, which may result in fluid leaking from the unit.

Action: Follow the attached supplier instructions to prevent any future fluid loss from the unit..

Note: Make sure Loctite 243 or an equivalent medium strength thread lock product is applied to the threaded section of the unions.

anBhdHRlcnM7MjAyNC0vOC0wN10xNDcyNzo1My43NzFaOzE0Ny4xNjEuMTY3LjEwNzsz=