

Reference	SSM76144
Models	F-PACE / X761
Title	Front End Accessory Drive Malfunction
Category	Engine
Last modified	25-Jul-2024 00:00:00
Symptom	499000 Basic Engine

Content **Model / Model Year / Derivative**

F-PACE / 21MY onwards / Ingenium I6 3.0L petrol

Situation:

Certain vehicles are experiencing split/damaged accessory drive belts and worn/damaged accessory drive belt tensioners and pulleys, resulting in abnormal noises coming from the engine bay.

Action:

With the engine running safely, and without risking causing any damage, record a video of any abnormal noises coming from the front end accessory drive belt area and submit the video within an Electric Product Quality Report (EPQR). The EPQR must make reference to PTS_100.

If a replacement accessory drive belt tensioner is required, then the accessory drive belt and accessory drive pulley should also be replaced at the same time.

Retain all removed parts. Engineering will contact your Retailer to organise collection of the parts for Engineering analysis.

(Ref 000333596)

anBhdHRlcnM7MjAyNC0wNy0yNVQxMjowNzoyMC41MjZaOzE2NS4yMjUuOS4xMDI7