
	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		

## Software-Over-The-Air (SOTA) Campaign Release Summaries


Please see below details of upcoming ‘Software-Over-The-Air’ (SOTA) campaigns:

### EVA2 SOTA release ‘4.1.5’ – Campaign summary


<b>Vehicle scope (Model Line &amp; MY)</b>	<p>21-23 MY Defender, I-Pace, Discovery, XE, XF</p> <p>24MY I-Pace, Discovery Sport, Range Rover Velar, Range Rover Evoque, E-Pace,</p> <p>25MY I-Pace</p>
<b>Module(s) affected</b>	<ul style="list-style-type: none"> <li>• Infotainment Gateway Module / Panasonic-In-Vehicle-Infotainment (PIVI)</li> <li>• Driver Assistance Domain Controller (DADC)</li> <li>• Image Processing Module (IPMA)</li> <li>• Audio Amplifier Module (AAM)</li> <li>• Combined Chassis Control Module (CHCM)</li> <li>• Power Steering Control Module (PSCM)</li> </ul>
<b>Improvements overview</b>	Enhancements to the following systems: Apple CarPlay/ Android Auto, ADAS, Steering
<b>Release type</b>	Minor update   Customer notified in-vehicle   Single bank experience (vehicle shutdown required)
<b>Customer impact</b>	Vehicle required to be shut down and locked for approximately 45 minutes
<b>Customer comms</b>	<ul style="list-style-type: none"> <li>• In-vehicle ‘What’s new?’ release summary</li> </ul>

	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		


<p><b>'What's new?' customer release summary</b></p>	<p><b>L663 (21 - 23MY)</b> This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Loss of steering assist on start-up.</li> </ul> <p><b>L663 (24MY)</b> This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Maps in the Driver Display may be replaced by a blank area.</li> <li>- Audio may continue to play after exiting the vehicle.</li> <li>- Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.</li> <li>- The interface for suspension ride height may freeze.</li> <li>- The last used radio station is incorrectly recalled on the next journey.</li> <li>- Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles.</li> <li>- New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.</li> <li>- Loss of steering assist on start-up.</li> </ul> <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> <li>- Touchscreen stability.</li> <li>- Bluetooth stability.</li> <li>- Apple CarPlay stability.</li> <li>- Improved stability feel on low friction surfaces.</li> </ul> <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p>
--	--

	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		


	<p><b>L462 (21 - 23MY)</b></p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <p>Loss of steering assist on start-up.</p> <p><b>L462 (24MY)</b></p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Maps in the Driver Display may be replaced by a blank area.</li> <li>- Audio may continue to play after exiting the vehicle.</li> <li>- Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.</li> <li>- The interface for suspension ride height may freeze.</li> <li>- The last used radio station is incorrectly recalled on the next journey.</li> <li>- Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles.</li> <li>- New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.</li> <li>- Loss of steering assist on start-up.</li> </ul> <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> <li>- Touchscreen stability.</li> <li>- Bluetooth stability.</li> <li>- Apple CarPlay stability.</li> <li>- Improved stability feel on low friction surfaces.</li> </ul> <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p>
--	---

	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		


	<p><b>X590 (21 – 24.75MY)</b>  This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Loss of steering assist on start-up.</li> </ul> <p><b>X590 (24.75 - 25MY)</b>  This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Maps in the Driver Display may be replaced by a blank area</li> <li>- Audio may continue to play after exiting the vehicle.</li> <li>- Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.</li> <li>- The last used radio station is incorrectly recalled on the next journey.</li> <li>- New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.</li> </ul> <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> <li>- Touchscreen stability.</li> <li>- Bluetooth stability.</li> <li>- Apple CarPlay stability</li> </ul> <p><b>X760 (21 - 24MY)</b>  This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Loss of steering assist on start-up.</li> </ul>
--	--

	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		


	<p><b>X260 (21 - 24MY)</b></p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Loss of steering assist on start-up.</li> </ul> <p><b>L560 (24MY)</b></p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Maps in the Driver Display may be replaced by a blank area.</li> <li>- Audio may continue to play after exiting the vehicle.</li> <li>- Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.</li> <li>- The interface for suspension ride height may freeze.</li> <li>- The last used radio station is incorrectly recalled on the next journey.</li> <li>- Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles.</li> <li>- New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.</li> </ul> <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> <li>- Touchscreen stability.</li> <li>- Bluetooth stability.</li> <li>- Apple CarPlay stability.</li> </ul> <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p> <p><b>L550 (24MY)</b></p>
--	---

	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		

	<p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Maps in the Driver Display may be replaced by a blank area.</li> <li>- Audio may continue to play after exiting the vehicle.</li> <li>- Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.</li> <li>- The interface for suspension ride height may freeze.</li> <li>- The last used radio station is incorrectly recalled on the next journey.</li> <li>- Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles.</li> <li>- New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.</li> </ul> <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> <li>- Touchscreen stability.</li> <li>- Bluetooth stability.</li> <li>- Apple CarPlay stability.</li> </ul> <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p> <p>.</p> <p><b>L551 (24MY)</b></p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Maps in the Driver Display may be replaced by a blank area.</li> <li>- Audio may continue to play after exiting the vehicle.</li> <li>- Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.</li> </ul>
--	--

	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		

	<ul style="list-style-type: none"> <li>- The interface for suspension ride height may freeze.</li> <li>- The last used radio station is incorrectly recalled on the next journey.</li> <li>- Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles.</li> <li>- New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.</li> </ul> <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> <li>- Touchscreen stability.</li> <li>- Bluetooth stability.</li> <li>- Apple CarPlay stability.</li> </ul> <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p> <p><b>X540 (24MY)</b></p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> <li>- Maps in the Driver Display may be replaced by a blank area</li> <li>- Audio may continue to play after exiting the vehicle.</li> <li>- Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.</li> <li>- The last used radio station is incorrectly recalled on the next journey.</li> <li>- New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.</li> </ul>
--	---

	Authored:	<b>Jun 2024</b>	Reference:	<b>SOTA S018</b>
	<b>SOTA Campaign Release Summaries</b>			
	Models:	<b>All SOTA-capable vehicles (EVA2)</b>		

	<p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"><li>- Touchscreen stability.</li><li>- Bluetooth stability.</li><li>- Apple CarPlay stability</li></ul>
--	--