
	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		

Software-Over-The-Air (SOTA) Campaign Release Summaries


Please see below details of upcoming ‘Software-Over-The-Air’ (SOTA) campaigns:

EVA2 SOTA release ‘4.1.5’ – Campaign summary


Vehicle scope (Model Line & MY)	<p>21-23 MY Defender, I-Pace, Discovery, XE, XF</p> <p>24MY I-Pace, Discovery Sport, Range Rover Velar, Range Rover Evoque, E-Pace,</p> <p>25MY I-Pace</p>
Module(s) affected	<ul style="list-style-type: none"> • Infotainment Gateway Module / Panasonic-In-Vehicle-Infotainment (PIVI) • Driver Assistance Domain Controller (DADC) • Image Processing Module (IPMA) • Audio Amplifier Module (AAM) • Combined Chassis Control Module (CHCM) • Power Steering Control Module (PSCM)
Improvements overview	Enhancements to the following systems: Apple CarPlay/ Android Auto, ADAS, Steering
Release type	Minor update Customer notified in-vehicle Single bank experience (vehicle shutdown required)
Customer impact	Vehicle required to be shut down and locked for approximately 45 minutes
Customer comms	<ul style="list-style-type: none"> • In-vehicle ‘What’s new?’ release summary

	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		


<p>'What's new?' customer release summary</p>	<p>L663 (21 - 23MY) This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Loss of steering assist on start-up. <p>L663 (24MY) This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Maps in the Driver Display may be replaced by a blank area. - Audio may continue to play after exiting the vehicle. - Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen. - The interface for suspension ride height may freeze. - The last used radio station is incorrectly recalled on the next journey. - Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles. - New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings. - Loss of steering assist on start-up. <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> - Touchscreen stability. - Bluetooth stability. - Apple CarPlay stability. - Improved stability feel on low friction surfaces. <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p>
--	--

	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		


	<p>L462 (21 - 23MY)</p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <p>Loss of steering assist on start-up.</p> <p>L462 (24MY)</p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Maps in the Driver Display may be replaced by a blank area. - Audio may continue to play after exiting the vehicle. - Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen. - The interface for suspension ride height may freeze. - The last used radio station is incorrectly recalled on the next journey. - Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles. - New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings. - Loss of steering assist on start-up. <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> - Touchscreen stability. - Bluetooth stability. - Apple CarPlay stability. - Improved stability feel on low friction surfaces. <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p>
--	---

	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		


	<p>X590 (21 – 24.75MY) This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Loss of steering assist on start-up. <p>X590 (24.75 - 25MY) This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Maps in the Driver Display may be replaced by a blank area - Audio may continue to play after exiting the vehicle. - Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen. - The last used radio station is incorrectly recalled on the next journey. - New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings. <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> - Touchscreen stability. - Bluetooth stability. - Apple CarPlay stability <p>X760 (21 - 24MY) This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Loss of steering assist on start-up.
--	---

	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		


	<p>X260 (21 - 24MY)</p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Loss of steering assist on start-up. <p>L560 (24MY)</p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Maps in the Driver Display may be replaced by a blank area. - Audio may continue to play after exiting the vehicle. - Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen. - The interface for suspension ride height may freeze. - The last used radio station is incorrectly recalled on the next journey. - Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles. - New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings. <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> - Touchscreen stability. - Bluetooth stability. - Apple CarPlay stability. <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p> <p>L550 (24MY)</p>
--	---

	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		

	<p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Maps in the Driver Display may be replaced by a blank area. - Audio may continue to play after exiting the vehicle. - Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen. - The interface for suspension ride height may freeze. - The last used radio station is incorrectly recalled on the next journey. - Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles. - New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings. <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> - Touchscreen stability. - Bluetooth stability. - Apple CarPlay stability. <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p> <p>.</p> <p>L551 (24MY)</p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Maps in the Driver Display may be replaced by a blank area. - Audio may continue to play after exiting the vehicle. - Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen.
--	--

	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		

	<ul style="list-style-type: none"> - The interface for suspension ride height may freeze. - The last used radio station is incorrectly recalled on the next journey. - Correction to the ride height dimensions in the 4x4i app 'dimensions' tab on applicable vehicles. - New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings. <p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none"> - Touchscreen stability. - Bluetooth stability. - Apple CarPlay stability. <p>PHEV only: Please note that for a short period of time, you may experience some disruption in your EV capabilities after the update has installed. Please disconnect the vehicle charger and ensure the battery has a minimum charge level of 25% before starting the update.</p> <p>X540 (24MY)</p> <p>This update includes a number of general interface and performance improvements as well as resolving the following specific issues. Thank you for your feedback.</p> <ul style="list-style-type: none"> - Maps in the Driver Display may be replaced by a blank area - Audio may continue to play after exiting the vehicle. - Apple CarPlay / Android Auto icon on the homescreen opens the incorrect screen. - The last used radio station is incorrectly recalled on the next journey. - New Speed limit Notification has moved from the Driver Assistance Menu to the Cruise and Limiter Menu. The audio notification can now be permanently set on/off in the new menu and is no longer affected by the Driver Assistance Settings.
--	---

	Authored:	Jun 2024	Reference:	SOTA S018
	SOTA Campaign Release Summaries			
	Models:	All SOTA-capable vehicles (EVA2)		

	<p>This update also brings improvements to the following features and systems:</p> <ul style="list-style-type: none">- Touchscreen stability.- Bluetooth stability.- Apple CarPlay stability
--	--