



STAR ONLINE PUBLICATION



Case Number: S2408000091

Release Date: August 2024

Symptom/Vehicle Issue: Tonale and Hornet Auxiliary Coolant Pump Locations "A", "B", "C"

Technician Observation: Auxiliary Coolant Pump Locations

Discussion: Pump Location Reference:


COOLANT PUMP "A" AUXILIARY ELECTRIC PUMP PECP2 which is named PECP2 (N213

COOLANT PUMP "B" AUXILIARY ELECTRIC PUMP PECP which is named PECP (N236

COOLANT PUMP "C" ADDITIONAL HEATER PUMP AHP which is named AHP (N238

Pump A

[N213 Air conditioning system auxiliary water electric pump \(ENGINE\)](#)



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.


Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.




STAR ONLINE PUBLICATION



Pump B N236 REAR AUXILIARY WATER PUMP (REAR)



Pump C N238 COCKPIT HEATING AUXILIARY PUMP (ENGINE)



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.