



STAR ONLINE PUBLICATION



Case Number: S248A000013

Release Date: August 2024

Symptom/Vehicle Issue: After Radio Software Update, Pedestrian Emergency Brake (PEB) Lamp and Forward Collision Warning (FCW) Lamp on in Cluster or Other Customer Programmable Features Concerns Not Set, No Diagnostic Trouble Codes (DTCs)

Discussion: Customer may complain after a radio software update that the PEB, FCW warning lamps on (no DTC) or a cluster programmable feature is not set correctly like language or units. These features may be programmed in the radio menu options, but might also require to go into the Instrument Panel Cluster (IPC), Misc Functions and run the "Customer Programmable Feature Configuration", see Star Online Publication S2108000249.

2022 WAGONEER/GRAND WAGONEER 6.4L V8 SRT HEMI MDS 13.00 Volts

1C4SJV44NS103601

IPC

Instrument Panel Cluster

Flash DTCs Data **Misc Functions** System Tests Actuators Details Configuration

NAME
Customer Programmable Feature Configuration

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.