



Bulletin No.: PIP5977
Published date: 05/2/2024

Preliminary Information

PIP5977 DTC P026D

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Express	2020 - 2022	All	All	2.8 LWN	All
GMC	Savana	2020 - 2022	All	All	2.8 LWN	All

Involved Region or Country:	North America, Israel
Condition:	Customer's concern may be of a Check Engine Light on with no drivability concerns noted.
Cause:	The dealer may find DTC P026D set in the ECM.

Correction:

Follow published diagnostics for DTC P026D.

If published diagnostics do not isolate a cause and the issue persists; the concern may be caused by a software anomaly.

Engineering is aware of the issue and is investigating.

If the vehicle is otherwise healthy clear the DTC and return the vehicle to the customer.

When a solution is identified, a bulletin will be released and this PI will be canceled.

Version History

Version	1
Modified	05/02/2024 - Created on.



GENERAL MOTORS