



Bulletin No.: PIP5979
Published date: 05/3/2024

Preliminary Information

PIP5979 P0089 P228C High Pressure Fuel Pump Internal Improvements Stall Hesitation Reduced Power

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2023 - 2024	All	All	1.5 LSD	All
GMC	Terrain	2023 - 2024	All	All	1.5 LSD	All

Involved Region or Country	North America
Condition	Vehicle may come into service department with a MIL with trouble codes P0089 and or P228C, stored as current or history. May also have symptoms of hesitation, stalling, and or reduced power.
Cause	High pressure fuel pump internal concern.

Correction:

Follow published diagnostics. You may need to replace the high pressure fuel pump. The high pressure fuel pump now has internal improvements to correct the setting of these two codes, as it relates to an internal pump issue.

Warranty Information

Version History

Version	1
Modified	05/03/2024 - Created on.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.