



Bulletin No.: PIT6168
Published date: 05/7/2024

Preliminary Information

PIT6168 DTC U3000 SYM57 Setting After Replacing Left Or Right Side Object Detection Control Module

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2023	All	All	All	All
Chevrolet	Corvette	2023 - 2024	All	All	All	All
Chevrolet	Silverado 2500HD/3500HD	2024	All	All	All	All
GMC	Canyon	2023	All	All	All	All
GMC	Sierra 2500HD/3500HD	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UFG / UFT / UKI / UKC / UKV / or UKW - Side Object Detection
Condition	A technician may find DTC U3000 SYM57 setting in the Left or Right Side Object Detection Control Module after replacing and programming has been completed.
Cause	The cause of the condition is a software anomaly that Engineering is aware of.

Correction:

Contact TAC for further direction.

Version History

Version	1
Modified	05/07/2024 - Created on.



GENERAL MOTORS