

Technical Service Bulletin (TSB)
Multiple Systems Repair Bundle Campaign

REFERENCE:	TSB: 08-180-24 GROUP: 08 - Electrical	Date:	August 10, 2024	REVISION:	—
VEHICLES AFFECTED:	2023 - 2024 (M6) Jeep Compass This bulletin applies to vehicles built on or after June 01, 2023 (MDH 0601XX) and on before June 30, 2024 (MDH 0630XX).			MARKET APPLICABILITY:	
				<input type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input checked="" type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: <ul style="list-style-type: none"> • Sunvisor lamp does not function. • Air Conditioning is not cooling. • No sound from the radio when in navigation mode. 				
CAUSE:	Manufacturing issue				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-114, date of issue August 10, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves performing multiple inspections based on the listed Customer Symptoms and possibly performing the associated Repair Procedure Operations.

USE THE FOLLOWING LABOR OPERATION NUMBERS AND TIME ALLOWANCES:

Labor Description / Check point / Inspections	Step	Labor Operation No.	Labor Time
Sun visor mirror lamp is not functioning and gap with roof. Perform Operation A1 if condition is confirmed.	A	08-60-02-90	0.1
Volume/sound is not functioning while in navigation mode. Perform Operation B1 if condition is confirmed.	B		
AC not cooling due to condenser leak Perform Operation C1 if condition is confirmed.	C		

NOTE: Perform only the operations associated with the operation code on Dealer Connect for the individual chassis.

Labor Description / Check point / Repairs	Operation	Labor Operation No.	Labor Time
Lamp, Sunvisor - Replace (0 - Introduction)	A1	08-60-02-91	0.2
Radio - Replace (0 - Introduction)	B1	08-60-02-92	0.6
Condenser, A/C - Replace (0 - Introduction)	C1	08-60-02-93	1.6
Failure Code	ZZ	Service Action	

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	7KU85SA5AB	Visor, W/Mirror	Passenger / Right
1 (AR)	7KU84SA5AC	Visor, W/Mirror	Driver / Left
1 (AR)	68461690AI	Radio, Multimedia	
1 (AR)	68273402AB	Condenser, Air Conditioning	

REPAIR PROCEDURE OPERATIONS:

Operation A1 – Replace the Sunvisor:

Refer to the detailed service procedures available in Dealer CONNECT> Service Library under: Service Info> 23 Body / Interior / Visor / Removal and Installation.

Operation B1 - Replace the Radio Assembly:

Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 08 Electrical / 8A Audio/Video/Entertainment/Connectivity / Radio / Removal and Installation.

Operation C1 - Replace the A/C Condenser:

Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 24 Heating and Air Conditioning / Plumbing / Condenser, A/C / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.