## STELLANTIS Technical Service Bulletin (TSB) Radio Over The Air Update from PARTS & SERVICES U29.28 and U33.9 to U33.43 Software Version August 10, 2024 TSB: 08-181-24 **REVISION:** REFERENCE: Date: **GROUP:** 08 - Electrical 2022 - 2024 (RU) Chrysler Pacifica / Voyager **VEHICLES MARKET APPLICABILITY:** This bulletin applies to vehicles equipped with one of the following: AFFECTED: $\times$ NA **MEA** • Uconnect 5 NAV W 8.4" Display (Sales Codes UBL or UEL) with a SA IAP Global Telematics Box Module (Sales Code RDG). Uconnect 5 NAV W 10.1" Display (Sales Codes UBN or UEN) with a EE CH Global Telematics Box Module (Sales Code RDG). **CUSTOMER** Customers may also experience one or more of the following: SYMPTOM: • Unable to select the Turn by Turn Navigation. Blank Performance Pages (Rearview Camera (RVC) Functions Normally). Android Auto Voice Recognition inoperative. Media Tuner delayed. Charge Schedule HMI (RVC Functions Normally). Ambient Light inoperative. Map in Cluster inoperative. Media Widget blank. Navigation Map black. Off road pages inoperative (RVC Functions Normally). VR inoperative. Incorrect song title displayed (Carplay® only). HU switches from Media Page to Home Page (RVC Functions Normally). Ghost Touch on Navigation screen (RVC Functions Normally).

### **REPAIR SUMMARY:**

CAUSE:

This bulletin provides information regarding the latest FOTA update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software will be updated from U29.28 or U33.9 to U33.43.

Various software issues due to the current software version of the radio.

Returns to wrong page after View Camera Event selected by customer in the "Camera View Pages" (RVC

NOTE: The Estimated National launch date is August 31, 2024.

Widgets missing.


New user profile does not load.

Functions Normally).

#### **DISCUSSION:**

Vehicles sold in the U.S. and Canada can now receive software updates "over-the-air". Updates to software will occur in a phased roll-out. The software is updated through a built in cellular modem in the vehicle. Customers will see a notification on their radio screen when new software is available for their radio Fig. 1. The owner will have the option to update the radio or schedule the update for later. There is not an option to decline the update indefinitely, the update must be performed.

NOTE: This is an Information Only Technical Service Bulletin to inform the dealer how the FOTA update is performed. This document does not contain a LOP for reimbursement.



**Fig. 1**Software Acceptance Screen

- 1. The vehicle needs to be in 'Park'. The ignition needs to be in the off position.
- If the customer selects "Update Now" Fig. 1 they can shut off the vehicle and leave. The update will be completed automatically.

NOTE: This step may take several minutes to complete.

3. Upon completion of update, the radio will display a confirmation message Fig. 2.




Fig. 2
Software Update Confirmation Screen

# **POLICY:**

# Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.