



Preliminary Information

PIT6055C HUMMER EV Service Driver Assist Message with DMS DTC: U3000 or B0126

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022 - 2024	All	12/11/2023	All	All
GMC	HUMMER EV SUV	2024	All	12/11/2023	All	All

Involved Region or Country	North America
Condition	<p>A customer may comment of a "Service Drivers Assist" message, upon inspection one or more of the following DTC's may be found in the K180 Drivers Monitoring System Module (DMSM).</p> <p>B0126 SYM 49 Current/History, U3000 SYM 44 Current/History, U3000 SYM 49 Current/History.</p> <p>Note: If you experience a Service Drivers Assist" message that does not have one of the following DTC's above, refer to normal SI diagnosis.</p>
Cause	Software Anomaly

Correction:

GM engineering has released software to address this concern which is part of a newly released software package. Please perform the latest version of [PIT6065](#) to resolve the concern.

Version History

Version	4
Modified	<p>09/12/2023 - Created on. 11/14/2023- Update PI to add software fix that is now available. 02/29/2024- Reinstated PI per request of the Brand Quality Manager. 05/10/2024- Updated PI to point the software fix to PIT6065 as part of a software package per BQM</p>



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.