



Preliminary Information

PIT5964B 2022 HUMMER EV Exterior Lamps Flicker Every 8 seconds Along With A Momentary Pause Of The Windshield Wipers And Turn Signal Click Clack Sound Effect With Current Or History DTC: P0607

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may experience one or more of the following concerns: <ol style="list-style-type: none">1. Exterior Lamps Flicker every 8 seconds2. Momentary pause of the windshield wipers3. Momentary pause of the turn signal indicator clicking sound effect4. Current or history code: P0607
Cause	The cause of this concern could be a K219 Lighting control module that is in boot mode (Logic Locked)

Correction:

GM engineering has released software to address this concern which is part of a newly released software package. Please perform the latest version of [PIT6065](#) to resolve the concern.

Version History

Version	3
Modified	01/04/2023 - Created on. 11/21/2023- Updated the correction. 05/13/2024- Updated correction.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.