



Bulletin No.: PIT6172
Published date: 05/13/2024

Preliminary Information

PIT6172 Diagnostic Tip : Perceived Speaker Rattle In Driver Door

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2023 - 2024	All	All	All	All
GMC	Canyon	2023 - 2024	All	All	All	All

Involved Region or Country:	North America
Condition:	Perceived speaker rattle in the driver door with radio playing.
Cause:	Noise from driver window switch.

Correction:

If this concern is duplicated do not replace the speaker, cover the window switch with your hand. If the noise is gone the switch is the issue. Engineering is aware of the concern and is working to resolve the issue.

Version History

Version	1
Modified	05/13/2024 - Created on.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.