



# Preliminary Information

## PIT6174 Instrument Panel Display Concerns

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2023	All	All	All	All
GMC	Canyon	2023	All	All	All	All

Involved Region or Country	United States, Canada, Mexico, Middle East, Cadillac Korea (South Korea)
Additional Options (RPO)	IVD
Condition	Customers may comment that the IPC display screen will intermittently freeze on the loading display.  Some customers may also comment that the speedometer will change from MPH to KPH intermittently.
Cause	These may be caused from radio software anomalies.

### **Correction:**

Please do not replace any parts at this time. Engineering is aware of these concerns. Once a correction is available, this PI will be updated.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3486108	Verifying freezing IPC, speed on IPC randomly changing from MPH to KPH or vice versa	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

### Version History

Version	1
Modified	05/15/2024 - Created On.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.