



Preliminary Information

PIP5965A 3.0L Diesel Setting DTC P138C

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2023 - 2024	All	All	LM2	All
Chevrolet	Suburban	2023 - 2024	All	All	LM2	All
Chevrolet	Tahoe	2023 - 2024	All	All	LM2	All
GMC	Yukon	2023 - 2024	All	All	LM2	All
GMC	Yukon XL	2023 - 2024	All	All	LM2	All

Involved Region or Country:	North America, Europe, Kazakhstan, Uzbekistan, Middle East Israel, Palestine, Argentina, Brazil, Bolivia, Chile, Columbia, Ecuador, Paraguay, Peru, Uruguay, Japan, Cadillac Korea, Philippines, Australia/New Zealand, Other Africa
Condition:	Some customers may comment of a malfunction indicator lamp illuminated. The technician may find P138C set in the ECM.
Cause:	This may be caused by a software anomaly

Correction:

Please update the ECM with the latest available calibration.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Version History

Version	2
Modified	4/8/2024



GENERAL MOTORS