



Preliminary Information

PIC6554 Steering Wheel Off-Center To Left When Driving Straight

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XT4	2024	May 13, 2024	May 17, 2024	All	All
Chevrolet	Malibu	2024	May 13, 2024	May 17, 2024	All	All

Involved Region or Country	North America
Condition	Some customers may find that the steering wheel is off level or tilted counter-clockwise (left) or some customers may comment that the vehicle pulls to the right while maintaining a straight heading on a typical straight road.
Cause	The cause may be an incorrect alignment setting from the factory.

Correction:

Perform a wheel alignment check and adjust steering wheel angle and toe.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*3086038	Perform Wheel Alignment and Adjust Steering Wheel Angle and/or Front Toe	0.7 hr
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	05/31/2024 - Created.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.