



Preliminary Information

PIT6152A HUMMER EV Service Driver Assist Message with DTC: B2BA1 Set In the K179 Automated Map Module

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022 - 2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPOs)	UKL Super Cruise
Condition	Some customers may comment that a "Service Driver's Assist" message (SDA) displays in the cluster over a key cycle. Technicians may also see that a DTC: B2BA1 is set current in the K179 Map Module but the customer may notice that super cruise still engages.
Cause	Software anomaly that is setting the B2BA1 that generates an SDA message.

Correction:

GM engineering has released software to address this concern which is part of a newly released software package. Please perform the latest version of PIT6065 to resolve the concern.

Version History

Version	2
Modified	04/18/2024 - Created on. 05/23/2024- Updated PI to point the software fix to PIT6065 as part of a software package



GENERAL MOTORS