



Bulletin No.: PIT6085B

Published date: 06/11/2024

Preliminary Information

PIT6085B Forward Collision Alert Unavailable Message

Models

Brand: GMC **Model:** HUMMER EV SUV 2024 **Model Years:** 2024 **VIN:** All **Engine:** All **Transmissions:** All

Involved Region or Country	North America
Condition	Some customers may state that they receive a "Forward Collision Alert Unavailable" message on the DIC and/or an orange telltale lamp after the vehicle is started
Cause	Software anomaly in the K124 Image Processing Module.

Correction:

Reprogram the K124 Image Processing Module using the latest software available in SPS which is part of Techline Connect.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information

Labor Operation	Description	Labor Time
2810825	K124 Image Processing Module Reprogramming with SPS	Use Published Time

Version History

Version	3
Modified	11/09/2023 - Created on. 05/13/2024- Updated correction. 06/11/2024- Update correction section

