



Bulletin No.: PIT6139C

Published date: N/A

Preliminary Information

PIT6139C HUMMER EV Service Driver Assist Message with DTC: B2BA1 Set In the K179 Automated Map Module

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	HUMMER EV	2022 - 2024	All	All	All	All
GMC	HUMMER EV SUV	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPOs)	UKL Super Cruise
Condition	Some customers may comment that a "Service Driver's Assist" message (SDA) displays in the cluster over a key cycle. Technicians may also see that a DTC: B2BA1 is set current in the K179 Map Module but the customer may notice that super cruise still engages.
Cause	Software anomaly that is setting the B2BA1 that generates a SDA message.

Correction:

GM engineering has released software to address this concern, please update both the K179 Map Module and the K124 Image Processing Module.


Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2811855	Automated Driving Mapping Module Reprogramming with SPS	Use Published Time
2810825	K124 Image Processing Module Reprogramming with SPS	Use Published Time

Version History

Version	4
Modified	03/21/2024 - Created on. 03/27/2024- Update PI to clarify correction statement 05/13/2024- Updated correction. 06/11/2024- Updated to remove reference to PIT6065G and add specific module programming.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.