



**Bulletin No.:** PIP5986

**Published date:** N/A

## Preliminary Information

### PIP5986 Diagnostic Tip:DTC P219A Set As Current Or History But Easily Duplicated

#### Proactive

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b>	<b>Engine:</b>	<b>Transmissions:</b>
			<b>from to</b>		
Chevrolet	Traverse	2024	All	All 2.5 LK0	All
GMC	Acadia	2024	All	All 2.5 LK0	All

<b>Involved Region or Country:</b>	North America
<b>Condition:</b>	DTC P219A set as current or history
<b>Cause:</b>	GM Engineering is aware of the condition and validating a repair

#### Correction

If you encounter DTC P219A that is set as current or easily duplicated complete steps 1-9 of the DTC P219A diagnostics in Service Information.

If issues are isolated during those steps please clear the code and advise that GM Engineering is aware of the condition and currently validating a repair.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description	Labor Time:
4088448	Engine Diagnostics	0.6 Hr.

#### Version History

<b>Version</b>	1
<b>Modified</b>	06/12/2024 - Created on.

GM Global Brands

© 2024 General Motors. All Rights Reserved.