



**Bulletin No.:** PIC6560

**Published date:** 06/14/2024

## Preliminary Information

### PIC6560 Diagnostic Tip - Excessive Wind Noise From Sunroof

#### Models


<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b> from to	<b>Engine:</b>	<b>Transmissions:</b>
Buick	Envista	2024 - 2025	All	All All	All
Chevrolet	Trax	2024 - 2025	All	All All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>Customer may comment on excessive wind noise heard with sunroof fully open at speeds greater then 30 mph.</b>
<b>Cause</b>	<b>The noise is heard when the sunroof is opened to the full position.</b>

#### Correction:

**This vehicle is equipped with 2 different sunroof open positions. The first is known as the comfort stop position, the sunroof will express open and stop approximately 2 inches short of fully open. The purpose of this position is to prevent excessive wind noise. The second position is known as the full open position and is obtain by pressing the sunroof express open a second time. See examples below for the comfort stop and full open positions.**

**If you encounter a complaint of excessive wind noise from the sunroof when in the full open position, no action should be taken as this is a normal condition. Please advise the customer to use the sunroof in the "comfort stop" position.**



## Comfort stop position



## Full open position

## Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*1086828	Confirm wind noise limited at sunroof comfort stop position	0.1 Hr.
*This is a unique Labor Operation for Bulletin use only.		

## Version History

Version	1
Modified	06/14/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.