



## **SSM 52783 2023-2024 Transit - Incorrect Front Bumper Inner Park Aid Sensor Catalog Part Number**

Some 2023-2024 Transit vehicles may require the front bumper inner park aid sensor (15K859) to be replaced in service. The service part number called out in the parts catalog for the sensors, NU5Z-15K859-AQPTM, is incorrect. If it is necessary to replace the front bumper inner parking aid sensors, order part number JU5Z-15K859-APT. The parts catalog will be updated to correct this change. If the incorrect sensor is installed, the park aid module (PAM) will be unable to complete the service calibration routine.